



UNITED STATES LIME & MINERALS, INC.

COLORADO LIME CO.
1468 HIGHWAY 50
DELTA, CO 81416
(970) 874-8300

Ground Calcium Carbonate - Rock Dust

Typical Chemical Analysis

Calcium Carbonate	> 88 %
Magnesium Carbonate	> 4 % < 8 %
Silica Dioxide	< 2.5 %
FE2O3	< 0.3 %
Al2O3	< 1.0 %
Sulfur	< 0.05 %

Typical Screen Analysis

Passing 50 Mesh	100%
Passing 100 Mesh	97% - 99%
Passing 200 Mesh	75% - 85%
Passing 325 Mesh	75% - 85%